



Reliable Connections™

## H-600, H-601 & H-614 Power Operators

### Important Instructions

**Air Required:** 90 cubic feet of free air per minute at 90 psi pressure (full load).

**IMPORTANT:** Maintain pressure of 90 psi. We recommend the use of a gage at the handle to determine the actual pressure of air at the air motor.

### Phone: (800) 423-1323

By deviating from the above listed instructions, you will void any product warranty and release Mueller Co. and its affiliated entities from any and all liability associated with the installation or use of this product. For details on the product's warranty, terms, and conditions, please visit [www.muellercompany.com](http://www.muellercompany.com).

© 2016 Mueller Co., LLC. All rights reserved.

Form 9164 04/16