

Centurion® Fire Hydrants

Bonnet Repair Kit

| Catalog ID | Description | Quantity |
|------------|-----------------------------------|----------|
| A-3 | Hold Down Nut O-Ring | 1 |
| A-5 | Bonnet O-Ring | 1 |
| A-6 | Anti-Friction Washer | 1 |
| A-85 | Wiper Ring | 1 |
| A-10 | Bonnet Flange Gasket* | 1 |
| A-10 | Bonnet Flange O-Ring* | 1 |
| A-12 | Stem O-Rings | 2 |
| A-51 | Hydrant Lubricating Oil (10.5 oz) | 1 |

^{*} Older hydrants used a gasket between the Bonnet and Upper Barrel. Newer hydrants used an O-Ring. Both are referenced as A-10 in the repair parts.

Phone: (800) 423-1323

By deviating from the above listed instructions, you will void any product warranty and release Mueller Co. and its affiliated entities from any and all liability associated with the installation or use of this product. For details on the product's warranty, terms, and conditions, please visit www.muellercompany.com.

© 2016 Mueller Co., LLC. All rights reserved.

Form 11109 05/16