

November 22, 2021

Re: Recommended Touch Up / Repair of Amercoat 370 Fast Dry Epoxy Coating – Mueller Co.

To whom it may concern,

The following procedure is recommended to touch up / repair hydrants coated with Amercoat 370 fast dry epoxy coating:

1. Remove surface contaminants by solvent wiping or other suitable means per SSPC-SP1 guidelines
2. Hand tool clean per SSPC-SP2 or power tool clean per SSPC-SP3 the affected area
3. Feather edges to intact coating, which cannot be lifted by probing with a dull putty knife
4. Uniformly abrade approx. 1 – 2 inches adjacent to repair area
5. Solvent wipe uniformly abraded intact coating to ensure abraded residue is removed
6. Apply Amercoat 370 or Amercoat One to the repair area to the specified DFT per data sheet guidelines, overlapping approx. 1 – 2 inches onto the uniformly abraded and solvent wiped intact coating

Please advise if there are any questions.

Sincerely,

*Maushall Fayard*

Marshall Fayard  
Area Technical Service Manager

**ORDER INFORMATION:**

To order PPG Amercoat 370 or Amercoat One contact  
Tim Young -PPG Birmingham via phone, fax or e-mail.

Phone 1-205-226-0991

Fax 1-205-226-0991

PAF9972@ppg.com