
MUELLER® Centurion® Tamper-Proof Operating Nut

Deters Theft and Vandalism

This simple, yet effective option fights three challenges to the fire hydrants in your system:

- Unauthorized operation
- Theft of parts
- Vandal inflicted damage to the operating and hold-down nuts

A ductile iron cap that spins freely on top of the hydrant bonnet shields the operating mechanism and protects it from would-be vandals. Common tools cannot grip the cap, the operating nut or the specially shaped hold-down nut. Only authorized utility and fire personnel will have the tools needed to operate the hydrant or to remove the cap and hold-down nut if the hydrant ever needs repair.



Tamper-Proof Fire Hydrants and Accessories

Tamper-Proof Option for 4-1/2" and 5-1/4" Mueller® Centurion® Hydrants (Factory Installed)



Option 114 - Centurion Fire Hydrant with installed Tamper-Proof feature for open left or open right. Specify "Option 114" on order.



Option 110 - Centurion Fire Hydrant with installed Tamper-Proof Cast Iron Hold-Down Nut only, for open left or open right. Specify "Option 110" on order.

4-1/2" and 5-1/4" Tamper-Proof Retrofit Kit


The following Kits fit 4-1/2" or 5-1/4" Centurion and Mueller Improved fire hydrants currently in use.

Item	Open Left Part Number	Open Right Part Number
Kit Complete	281904	281905
Bonnet O-Ring	142779	142779
Hold-Down Nut	145507	145565
Operating Nut Cap	145548	145549
Ring Retainer	145553	145553
Operating Nut	145554	145555
Retaining Clip	145557	145557
Hold-Down Nut O-Ring	194898	194898
Anti-Friction Washer	195546	195546

Wrenches for 4-1/2" and 5-1/4" Tamper-Proof Hydrants



A-391
Operating Nut Wrench
Used to assemble and disassemble
the Tamper-Proof Hold-Down Nut.



A-374

Operating Wrench

Operates the Tamper-Proof Hydrant and removes Hose and Pumper Nozzle Caps. (Also operates hydrants without tamper-proof feature).



Main Office — Decatur, IL Water Division: 800-423-1323 www.muellercompany.com Canada — Mueller Canada Inc., Milton, Ontario 905-878-0541