

**Centurion® Fire Hydrants** 

## **Reliable Connections**<sup>®</sup>

## **Shoe Repair Kit Contents**

Catalog ID	Description	Quantity
A-34	Drain Valve Facings	2
A-35	Drain Valve Facings Screws	4
A-38	Drain Ring Housing Gasket	1
A-39	Top Seat O-Ring	1
A-44	Bottom Seat O-Ring	1
A-45	Main Valve – Reversible	1
A-47	Cap Nut Seal	1
A-48	Lock Washer	1
A-37	Shoe Bolts	6
	Shoe Drain Ring Nuts	8
A-41	Drain Ring Bolts	2
A-51	Lubricant	1
A-46	Lower Valve Plate	1

## Phone: (800) 423-1323

By deviating from the above listed instructions, you will void any product warranty and release Mueller Co. and its affiliated entities from any and all liability associated with the installation or use of this product. For details on the product's warranty, terms, and conditions, please visit www.muellercompany.com.

© 2016 Mueller Co., LLC. All rights reserved.

Form 11110 02/16